

2737

A181442

**R** and **CENTER**  
**LABORATORY**  
**TECHNICAL REPORT**

NO. 12653



FABRICATION OF T-156 TRACK BUSHING ASSEMBLIES

FINAL REPORT

JULY, 1982

U. S. ARMY

TANK - AUTOMOTIVE COMMAND

CONTRACT NO. DAAE07-81-C-4095

by C. E. LYNN

THE GOODYEAR TIRE & RUBBER CO.  
P. O. BOX 288  
ST MARYS, OHIO 45885

APPROVED FOR PUBLIC RELEASE - DISTRIBUTION UNLIMITED

**U.S. ARMY TANK-AUTOMOTIVE COMMAND**  
**RESEARCH AND DEVELOPMENT CENTER**  
**Warren, Michigan 48090**

20071025300

AM-433911

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER 12653	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle)  Fabrication of T-156 Track Bushing Assemblies		5. TYPE OF REPORT & PERIOD COVERED Final
		6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(s)  Charles E Lynn		8. CONTRACT OR GRANT NUMBER(s)  DAAE07-81-C-4095
9. PERFORMING ORGANIZATION NAME AND ADDRESS The Goodyear Tire & Rubber Company P. O. Box 288 St Marys, Ohio 45885		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS  DD Form 1423
11. CONTROLLING OFFICE NAME AND ADDRESS U. S. Army Tank - Automotive Command DRSTA-RCKT 6501 East Eleven Mile Road, Warren, Michigan		12. REPORT DATE July 1982
		13. NUMBER OF PAGES 9
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		15. SECURITY CLASS. (of this report)  Unclassified
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)  Distribution Unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number)  Components Process Rubberizing		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number)  This report gives a brief description of the manufacturing process for rubberizing 1500 T-156 pins according to drawing P3-18483		



## SUMMARY

The Goodyear Tire & Rubber Company, a manufacturer of component products for military tracked vehicles, rubberized 1500 T-156 track shoe pins (Ref Dwg 12274418) to a given configuration as shown on Dwg P3-18483.

Material used in the rubberization process was Goodyear's QPL rubber - SM7541 as specified on Dwg P3-18483.

Materials and processing were monitored according to Military Specification Mil-T-11891 and Goodyear's QCI - No. 25.

Manufacturing technology applicable to this part is similar to that used in the fabrication of other military track-shoe-pin bushing assemblies.

TABLE OF CONTENTS

Page No.

Summary	2
Objective	4
Description of Assembly Procedure	5
Conclusion	6
Physical Testing Results	7
Distribution Statement	8
Drawings	9




OBJECTIVE

The purpose is to identify the manufacturing processes of a T-156 track shoe bushing assembly and denote problem areas within that procedure.

An independent contractor, not an agent of the Government, shall provide the personnel, materials and manufacturing facilities to fabricate 1,500 T-156 track pins and rubberize them per drawing P3-18483.

# DESCRIPTION OF ASSEMBLY PROCEDURE

The description of assembly procedures is presented in the following flow chart.



## CONCLUSION

The assembly and molding process for the 1,500 T-156 track-shoe-pin bushing assemblies was accomplished at the manufacturing facilities of The Goodyear Tire and Rubber Co., St Marys Plant, St Marys, Ohio.

No particular problems were encountered in any of the various production processes.

All phases were monitored under Mil-T-11891 and Goodyear's QCI 25.



## PHYSICAL TESTING RESULTS

### Shot Peening Intensity Values

(Checks per MIL-S-13165 to 0.010 A to 0.020# A)

Results: 0.012 - 0.013 Range

Average Value - 0.0125

### Bushing Adhesion Pull Values

(Checks per MIL-T-11891 - Outer Bushings - 33 lb/min)  
- Inner Bushings - 37 lb/min)

Results: 40 - 65 Range - Inner

Average Value - 52 lb

Results: 34 - 62 Range - Outer

Average Value 50 lb

TABLE OF DISTRIBUTION

COPIES

A. Department of Defense

2

Defense Documentation Center  
Attn: TIPDR  
Cameron Station  
Alexandria, VA 22314

B. Department of the Army

Commander  
U. S. Army Tank - Automotive Command  
Warren, Michigan 48090  
Attn: DRSTA-RCKT  
DRSTA-IREC  
Technical Service Library

10  
1  
2

C. Administering Contract Office (ACO)

1

DCASMA, Cleveland  
A J Celebreeze Federal Building  
1240 East Ninth Street  
Cleveland, Ohio 44199  
Attn: Ignacio Cardenas, Contracting Officer

DRAWINGS

Attachment I - Dwg No. P3-18483, Rev 3, Dated 1-20-81

Attachment II - Dwg No. 12274418, Rev C, Dated 5-12-80



**NOTE:**

L. MATERIAL: RUBBER QPL - SM 7541  
GOODYEAR TIRE & RUBBER Co.  
ST. MARYS. OHIO


## 2. TOLERANCE

3. WORK PERFORMED UNDER CONTRACT.  
Nº. DAAK30-79-C-0143

REV. 2	2-6-80	DIM. (2) WAS 1.855" DIM. (2) WAS 1.002" DIMS. (4) WERE .855" DIM. (5) WAS 1.030" NOTE ADDED. CEL 4-7-82	REV. 3 LYNN 1-20-81 DIM. WAS 1.090 - 2 PLACES CEL 1-20-81	JAN 1-15-80 STATIC WIRES AND RESPECTIVE NOTES REMOVED CEL 1-15-80	DIM. (2) WAS 1.855" DIM. (2) WAS 1.002" DIMS. (4) WERE .855" DIM. (5) WAS 1.030" NOTE ADDED. CEL 4-7-82	REV. 2 2-6-80 DIM. (2) WAS 1.855" DIM. (2) WAS 1.002" DIMS. (4) WERE .855" DIM. (5) WAS 1.030" NOTE ADDED. CEL 4-7-82
--------	--------	--	---	--	--	--



REVISIONS		DESCRIPTION	DATE	APPROVED
B		REDRAWN WITHOUT CHANGE WAS 1" SIZE PER ECP XM-A003	7-7-78	
		DWG APPVL SGNR ADDED		
C		1) NOTE 8 REMOVED (2) NOTE 6 REVISED		
B		ECP A511		



- QUALITY ASSURANCE REQUIREMENTS  
MAY APPLY TO THIS DRAWING.  
PART NO. SAME AS PART NO.
2. REMOVE ALL BURRS AND SHARP EDGES
3. IF STRAIGHTENING IS REQUIRED IT  
MAY BE PERFORMED AT  
ROOM TEMPERATURE
4. SHOT PEEN ENTIRE PIN, EXCEPT ENDS MAY BE UNPEENED,  
PER SPEC MIL-S-13165 TO 010A TO 020A,  
95% MINIMUM COVERAGE MEASURED  
BY POLISHED ARC HEIGHT STRIP
5. SURFACE ROUGHNESS VALUES ARE  
PRIOR TO SHOT PEENING
6. NO TOTAL AND NOT MORE THAN .005 PARTIAL  
DECARBURIZATION PERMITTED BEFORE SHOT PEENING
7. HEAT TREATMENT:  
QUENCH AND TEMPER  
AS QUENCHED HARDNESS 52 RC MIN  
AS TEMPERED HARDNESS 40/45 RC
8. MATERIAL:  
STEEL ALLOY BAR 8650H,  
SPEC ASTM A322 OR A331.
- NOTES:

[illegible]

XA-ECF  
A6511